16_08 D&C Computing RoW Markers

Question:

I used the D&C compute tool to check and an estimate. D&C manager picked up everything except row monuments. Why is this?

Answer:

There are two (2) types of right of way markers.

- type 1 iron pin and cap (triangle) design and computation payitem ddb **will not** count/compute this item.
- type 2- concrete or granite (circumscribed triangle) design and computation payitem ddb **will** count/compute this item.